FIRE SAFETY CERTIFICATE TRANSLATED COPY

No. C.NO/32/NOC/DFO/BELAGAVI/2023

Dated: 15-11-2023

Certified that the existing building Bhashini International School at Mandoli at Survey No. 24/2, Next To Mandoli Kaman, Mandoli, District Belagavi owned/occupied by Bhashini International School have complied with the fire prevention and fire safety requirements in accordance with rule of State/ UT Fire Service Rules, and verified by the officers concerned of Fire Service on 15-11-2023 (date of inspection) in the presence of The Secretary Bhashini International School, Mandoli, Belagavi and that the building/premises is fit for occupancy up to classes I to X (X/ XII) with effect from 15-11-2023 for a period of 1 years in accordance with rule and subject to compliance of the specific conditions as appended:-

- 1. One water mist extinguisher of 09 Ltrs capacity should be kept near each staircase landing.
- 2. One mechanical foam extinguisher of 09 Ltr capacity & one ABC type extinguisher of 06 kgs capacity should be provided near the diesel generator.
- 3. One Co2 type fire extinguisher provided near each electrical panel board & electrical room.

Issued on 15-11-2023 (date of issue) at Office of the District Fire Officer (place) by

BHASHINI INTERNATIONAL SCHOOL 24/2, Next to Mandoli Kaman. Mandoli, Belagavi - 590 008.

To,

Bhashini International School,

Survey No: 24/2, Next to Mandoli Kaman,

Mandoli, Belagavi 590008 Phone No: 9741300678

ENDORSEMENT

Signature with Seal Mr. Shashidhar S. Nilgar District Fire Officer BELAGAVI FIRE STATION

CHAIRMAN

BHASHINI INTERNATIONAL SCHOOL 24/2, Next to Mandoli Kaman, Mandoli, Belagavi - 590 008.

The No Objection Certificate issued by Fire Service with Condition and compliance of the above recommendation in column-4 of serial-B within 03 months and compliance to the undersigned.

> District Fire Officer (Karnataka State Fire and Emergency Services Belagavi-01)

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.

K. V. TORANGATTI B.Sc., LL.B. (Spl)

Advocate & Notary BELAGAVI

Office of the District Fire Officer

Karnataka State Fire and Emergency Services Khanapur Road, Belagavi-590001



Phone: 0831-2429441 E-Mail: dfobgv@gmail.com

Date: 15-11-2023

C.NO/32/NOC/DFO/BELAGAVI/2023

The Principal, Bhashini International School, Mandoli Villege, Belagavi, Belagavi Taluk & District.

Sir.

Sub: Issue of 'NOC' only to the ground floor of "The Bhashini

International School," Mandoli Villege, Belagavi, Belagavi Taluk &

District in which the 2nd & 3rd floor is under construction.

Ref: 1) Applicant Request Letter Dated: 09/11/2023

*_**_*_*_*

With reference to the subject above cited, the premises of "The Bhashini International School", building consisting with Ground and 2 Upper floors situated at Mandoli, Belagavi, Belagavi Taluk & District was inspected by fire District Fire Officer, Belagavi on 09-10-2023 with respect to fire Prevention, Fire fighting and Evacuation measures to be complied in the above premises and found that only the ground floor has been completed and is under use and the installation has been done for the ground floor and the 2nd & 3rd floor are still under construction.

ANNEXURE-1

(Up to 14.99 mtrs. In height)

"GROUP-B Educational Buildings

NBC-2016, Part-4, Table 7 (11) 3.1.3 Group B Educational Buildings Sub division B1 & B2.

(These condition are indicative and not exclusive all relevant provisions related to fire and life safety of NBC 2016 are mandatory.)

COTON.	Details of the Building/Premises.	
01	Name and Address of the Applicant	The Principal,
		Bhashini International School,
		Mandoli Villege, Belagavi,
		Belagavi Taluk & District.
02	Name and Address of the Premises	Bhashini International School,
		Mandoli Villege Belagavi,
		Belagavi Taluk & District.
03.	Name and Address of the Building	The President
	Owner	Sri. Mahantesh Shivanand Saboji
		Bhagya Nagar, Belagavi,
		Belagavi Taluk & District
04.	Number of Building	01
05.	Number of Floors	Ground & 2 Upper floors
06. Floorwise details of Accupancy:-		
	Ground Floor	Officer Room-01, Staff Room-01, Class Room-
		13, Mid Day Meal Room-01, Computer Lab-01
	45	& Lab Room-01

2 nd Floor of the building a p area of each floor: Ground floor 1 st Floor 2 nd Floor guilt-up area Inding properties:- East	Under construction 11.70 Mtr 6076.57 Sq Mtr 1004.24 Sq Mtr 1004.24 Sq Mtr 1004.24 Sq Mtr 3012.72 Sq Mtr
p area of each floor:- Ground floor 1 st Floor 2 nd Floor guilt-up area anding properties:-	6076.57 Sq Mtr 1004.24 Sq Mtr 1004.24 Sq Mtr 1004.24 Sq Mtr 3012.72 Sq Mtr
Ground floor 1st Floor 2nd Floor quilt-up area anding properties:-	1004.24 Sq Mtr 1004.24 Sq Mtr 1004.24 Sq Mtr 3012.72 Sq Mtr
Ground floor 1 st Floor 2 nd Floor guilt-up area anding properties:-	1004.24 Sq Mtr 1004.24 Sq Mtr 3012.72 Sq Mtr
1 st Floor 2 nd Floor suilt-up area anding properties:-	1004.24 Sq Mtr 1004.24 Sq Mtr 3012.72 Sq Mtr
2 nd Floor wilt-up area anding properties:-	1004.24 Sq Mtr 3012.72 Sq Mtr
uilt-up area	3012.72 Sq Mtr
inding properties:-	
	06 00 Mtr Road
	06 00 Mtr Road
	OO.OO IVIII ICOUG
West	Agricultural Land
North	Open Place
South	Open Place
Space all around the	
East	10.00 Mtr
West	01.00 Mtr
North	70.00 Mtr
	20.00 Mtr
	East West

B.On the inspection of this School/College premises, the following Fire Prevention, Fire Fighting and Evacuation Measures recommended are considered absolutely essential from fire safety point of view:-

Sl. No (01)	Details (02)		Existing (03)	,	Recommendations (04)
01.	Accessibility to the premises	The premises is accessible from 06.00 Mtr road on the Southern Side		thern Side	-
02.	Number of Entrances	One entrance of 12.00 mtr wide.		ntr wide.	-
03.	Number of Staircase	No of staircase	02 Nos		Staircase should be free from any obstructions.
		Width of the staircase	01.50 Mtr	01.50 Mtr	
/×	क्रिन्ध हैं	Width of threads	0.30 Mtr	0.30 Mtr	
3	et a	Height of risers	0.13 Mtr	0.13 Mtr	
SE SE		No of risers per flight	12	12	
1 Si	GO500, 35.	Height of the hand		44.07	
		drill.	L		(b) ou

04.	Portable	02 Nos. of 04 Kg Capacity ABC type	A. One water mist extinguisher of 09
	Extinguishers	Extinguisher And 02 Nos. of 02 Kg	Itrs capacity should be kept near each
		Capacity ABC type Extinguishers has	staircase landing.
		been provided in the ground floor.	B. One mechanical foam extinguisher
		occii provided in the ground noor.	of 09 ltr capacity & one ABC type
			extinguisher of 06 kgs capacity should
			be provided near the diesel generator.
			C. One CO2 type fire extinguisher of
			4.5 kgs capacity should be provided
			near each electrical panel board &
			electrical room.
			D. One ABC type fire extinguisher of
			06 Kgs capacity should be located as
			to be available within 15 mtrs. Radius
			In rest of the building after completion
			of construction.
0.5	Hose reel hose	Not Provided	One Hose reel hose near the staircase
05.		Not Flovided	(One hose reel hose system for every
	system		1000 sq.mtrs). The hose reel hose of
			min 19 mm size and of 30 mtrs length
			shall be provided to reach the farthest
			point of each floor and shut off branch
			having a nozzle of 05 mm size. The
		· ·	hose reel hose should be connected at
			each landing.
06.	At the terrace	Not Provided	The system should be connected to an
	tank level with		booster pump of 450 LPM or of 5 HP
	minimum		capacity.
	pressure of 3.5		Further the system should be
	kg/cm2		connected to an alternative source of
		No Position	power supply.
07.	Diesel	Not Provided	Diesel generator of 15 KVA capacity
	Generator		should be provided to supply
			alternative power supply.
08.	Terrace Tank	02 Nos. of 2000 Ltr capacity	The system should be connected to an
		overhead tank provided.	over head tank of 5000 ltrs capacity
			further if basement is provided the
			tank capacity shall be increased to
			10,000 ltrs capacity. (The water
			tank should be kept exclusively for
			fire fighting purpose.) to each Block.
	838 200		Note: if the existing building is not
1 /	19		capable of sustaining the weight of
1 //	of mella	* \\	5,000/10,000 ltrs tank capacity
1 113	1 发现3	11	provision shall be made to provide
1/35	1 (3388)	(8)	water tank on the side of the building
	1 0000 /65		with support from ground level by
1	100	A second	providing RCC column structure or
	Les ROSen		MS column structure.
			If there is no option to provide even
			the above mentioned overhead tank
			provision shall be made to provide
			underground water tank of capacity
1	7 79	1	with submersible pump of 5-7 HP
		0.11	eapacity.
-			A

A SHARE

09.	Escape routes	Marked only in the ground floor.	Direction in which the students have to move in the event of an emergency should be displayed in the corridor on each floor during evacuation.	
10.	Fire Order (Fire safety plans)	Not Displayed	A notice board indicating the action to be taken by the employees in case of any emergency should be displayed with the telephone numbers of Belagavi fire station i.e 0831-2429441. 101 & 080-22971550, 22971500, 22971600 and the telephone nos nearest ambulance services and police station.	
11.	No Smoking board	Displayed in the ground floor.	COPTA Sec-4 direction of No Smoking area, smoking here is an offence board should be written in English & Kannada both languages shall be prominently displayed at inside the entry/exit of the each floor.	
12.	Fire Siren	A Fire Siren has been installed in the premises to inform the inmates in case of a fire emergency and evacuate the area.	Complied	
13.	Nominate One Fire Nodal Officer	Mrs. Sapana Mathad & Mrs Geeta Jain has been nominated as the Fire Nodal Officer.	Complied.	
14.	Fire Fighting Training	Not Imparted	At least 40% of the Teaching and non Teaching staff should be got trained in basic fire fighting at R.A.Mundkur Fire & Emergency Services Academy, Bannerughatta Road, Bangalore or Regional training centre.	

Fire Precautionary Measures

A: Explosive and flammable materials should not be stored in the store room, UPS room, Electrical panel area, class rooms, laboratory & electrical sum panel premises.

B:- Accumulation of combustible waste in and around the premises should be avoided.

C:- The Exit ways shall be always kept clear without any obstruction.

D:- Liquefied petroleum gas should not be stored in the building.

E:- The doors shall not be kept locked/latched during working hours and shall be free from obstruction.

F:- During the class hours the class room door shall not be locked from inside to out side.

G:- As per Honorable Supreme Court order all teachers and staff shall be trained to handle safety equipments, initiate emergency evacuation and protect their students in the event of fire and other emergency and the school shall observe the Fire Safety Day on April 14th of every year by conducting Fire Safety drills with co-ordination with the fire services department.

Under the above circumstance the Karnataka Fire & Emergency Services Department is issuing "NOC" to "The Bhashini International School", Mandoli Village, Belagavi, Belagavi Taluk & District only to the ground floor as they have done installation in the ground floor and subjected to condition and compliance of the above recommendations in the column-4 of serial-B within 03 months and compliance to undersigned in the rest of the building.

This "NOC" is valid for only one year from the date of issue.

District Eire Officer

Karnataka State Fire And Emergency Services

Belagavi-01.

Yours Eaithfully