

TRANSLATED COPY
BUILDING SAFETY CERTIFICATE

No. PWD/Sub.Div,Bgm/D.M./S.K.S.P.P/2023-24/1416

Dated: 07-11-2023

Certified that the existing building **Bhashini International School at Mandoli at Survey No. 24/2,Next To Mandoli Kaman, Mandoli, District Belagavi** owned/occupied by Bhashini International School have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of The **Asst. Executive Engineer, Sub Division – 01 Belagavi PWD Belagavi** on **07-11-2023** in the presence of **The Secretary Bhashini International School, Mandoli, Belagavi** and that the building/premises is fit for occupancy up to classes **I to X (X/ XII)** with effect from **07-11-2023** for a period of 1 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Immediately report to the competent authority if any problem of collapse/crack/water leakage etc. is found in any part of the building in the next few days.
2. Proper maintenance of original building documents.
3. The said building is coming up in an urban area and according to the government circular for issue of building safety certificate Rs. 1000/- to be paid to this office.

Issued on 07-11-2023 at Asst. Executive Engineer, Sub Division -1 Belagavi by

Suhash V. Naik

PRINCIPAL

**BHASHINI INTERNATIONAL SCHOOL
24/2, Next to Mandoli Kaman,
Mandoli, Belagavi - 590 008.**

To,

Principal,
Bhashini International School,
Survey No. 24/2,Next To Mandoli Kaman,
Mandoli, Belagavi 590008

Signature with Seal

Name: **Mr. Suhash V. Naik**Designation: **Asst. Executive Engineer**Name & Office: **Sub Division -1 Belagavi**

Mahesh

CHAIRMAN

**BHASHINI INTERNATIONAL SCHOOL
24/2, Next to Mandoli Kaman,
Mandoli, Belagavi - 590 008.**

Note: This certificate should be signed / issued by Assistant Engineer & above officer of concerned Govt. Department only

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English is uploaded along with the original vernacular certificate as a single pdf.



ATTESTED BY

K.V.

K. V. TORANGATTI
B.Sc., LL.B. (Spi)
Advocate & Notary
BELAGAVI

ಕರ್ನಾಟಕ ಸರ್ಕಾರ
(ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ)

ಕ್ರ.ಸಂ.ಲೋ.ಇ./ಉ.ವಿ.ಬೆ./ಡಿ.ಎಂ/ಶ.ಕ.ಸು.ಪ್ರ.ಪ/2023-24/

7416

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು,
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ,
ಉಪ ವಿಭಾಗ, ಬೆಳಗಾವಿ ಇವರ ಕಚೇರಿ.

7/11/2023

ಇವರಿಗೆ,

Principal
Bhashini International School
Mandoli Tq, Belagavi

ಮಾನ್ಯರೇ,

ವಿಷಯ: ಕಟ್ಟಡ ಸುರಕ್ಷತೆ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡುವ ಕುರಿತು.

ಉಲ್ಲೇಖ: 1) ಸರ್ಕಾರದ ಸುತ್ತೋಲೆ ಸಂ: ಲೋ.ಇ/59 ಬಿಇಡಿ/2019
ದಿನಾಂಕ:06-05-2022.

2) ತಮ್ಮ ಅರ್ಜಿ ದಿನಾಂಕ 07-11-2023.

ಮೇಲ್ಕಾಣಿಸಿದ ವಿಷಯ ಹಾಗೂ ಉಲ್ಲೇಖಿತ ಪತ್ರ (1) & (2)ರನ್ವಯ, Bhashini International School Survey No. 24/2, Next to Mandoli Kaman, Mandoli, Belagavi ಶಾಲಾ ಕಟ್ಟಡದ ಸುರಕ್ಷತೆ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡುವಂತೆ ವಿನಂತಿಸಿರುತ್ತೀರಿ.

ಸದರಿ ಶಾಲಾ ಕಟ್ಟಡ ಸುರಕ್ಷತೆ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡುವ ಕುರಿತು ದಿನಾಂಕ: 07-11-2023. ರಂದು ಶಾಲಾ ಕಟ್ಟಡವನ್ನು ಪರಿವೀಕ್ಷಣೆ ಮಾಡಲಾಗಿ, ಕಟ್ಟಡವು ನೆಲ ಮಹಡಿ, ಮೊದಲನೇ ಮಹಡಿ, ಹಾಗೂ ಎರಡನೇ ಮಹಡಿ ಹೊಂದಿದ್ದು, ಕಟ್ಟಡವು ಸೂಸ್ಥಿತಿಯಲ್ಲಿದ್ದು, ಈ ಕೆಳಕಂಡ ಷರತ್ತುಗಳಿಗೆ ಒಳಪಡಿಸಿ ಕಟ್ಟಡವು ತರಗತಿಗಳನ್ನು ನಡೆಸಲು ಯೋಗ್ಯವಾಗಿದೆ ಎಂದು ಪ್ರಮಾಣೀಕರಿಸಲಾಗಿದೆ. ಸದರಿ ಪ್ರಮಾಣ ಪತ್ರವು ಸನ್ 2023-24 ನೇ ಸಾಲಿಗೆ ಮಾತ್ರ ಅನ್ವಯಿಸುತ್ತದೆ. ಇದನ್ನು ತಮ್ಮ ಮುಂದಿನ ಕ್ರಮಕ್ಕಾಗಿ ಕಳುಹಿಸಲಾಗಿದೆ.

ಷರತ್ತುಗಳು :

- 1 ಮುಂದಿನ ದಿನಗಳಲ್ಲಿ ಕಟ್ಟಡದ ಯಾವುದೇ ಭಾಗದಲ್ಲಿ ಕುಸಿತ/ಬಿರುಕು/ನೀರು ಸೋರುವಿಕೆ ಇತ್ಯಾದಿ ತೊಂದರೆಗಳು ಕಂಡು ಬಂದಲ್ಲಿ ಸಕ್ಷಮ ಪ್ರಾಧಿಕಾರಕ್ಕೆ ಕೂಡಲೇ ವರದಿ ನೀಡುವುದು.
- 2 ಕಟ್ಟಡದ ಮೂಲ ದಾಖಲೆಗಳನ್ನು ಸರಿಯಾಗಿ ನಿರ್ವಹಿಸುವುದು.
- 3 ಸದರಿ ಕಟ್ಟಡವು ಗ್ರಾಮೀಣ ಪ್ರದೇಶದಲ್ಲಿ ಬರುತ್ತಿದ್ದು, ಸರ್ಕಾರದ ಸುತ್ತೋಲೆ ಪ್ರಕಾರ ಕಟ್ಟಡ ಸುರಕ್ಷತೆ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ವಿತರಿಸಲು ರೂ. 1000/- ಗಳ ಶುಲ್ಕವನ್ನು ಈ ಕಛೇರಿಗೆ ಭರಣಾ ಮಾಡುವುದು.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು,
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ,
ಉಪ ವಿಭಾಗ ನಂ.1, ಬೆಳಗಾವಿ